

Cee-Bee[®] A-918

Cee-Bee[®] A-918 is a wipe solvent used to remove fingerprints, rubber and primer residues, marking inks, wax films, oils and grease from metal surfaces. Cee-Bee[®] A-918 is also good in removing label/adhesive residues.

Conforms To

- AMS
 - AMS 1526C (Partial)
- Boeing
 - BAC 5750
 - D6-17487, Rev. P

Benefits

- Alternative solvent to MEK.
- High solvency for most organic soils.
- Readily removes paint residues and rubber adhesives.
- Excellent for preparing old painted surfaces for paint-over.
- Effective solvent for use in ultrasonic cleaning processes.
- Safe for use on all common structural metals, including steel, high strength steel, aluminum, magnesium and copper.
- Non-photochemically reactive - does not contribute to air pollution.
- Low vapor toxicity.

Properties

- Colorless, water thin liquid
- Mild odor
- Blend of organic solvents

Notes Prior to Handling

Before using your Cee-Bee[®] products, all safety and operating instructions should be read and understood. If you have any questions, please contact your Cee-Bee[®] representative before proceeding.

Use Procedure

Removal of Soils and Paint, Rubber and Primer Residues

1. Wipe the surface clean using clean cloth or nylon fleece scrubbing pads wet with Cee-Bee[®] A-918. Turn frequently to prevent re-deposition of soil and/or paint residues on cleaned surface.
2. Allow to air dry or wipe with clean, dry cloths.

Preparation of Old Paint for Paint-Over

1. With clean cloth or nylon fleece scrubbing pads wet with Cee-Bee[®] A-918, wipe away soils and oxidized paint from surface. If surface remains tacky, use a final wipe with a clean cloth dampened with cleaner.

Clean Spray Pot/Gun After Paint Spraying

1. Clean spray pot with Cee-Bee[®] A-918.
2. Fill spraying pot with some Cee-Bee[®] A-918.
3. Spray Cee-Bee[®] A-918 out from pot until the spraying nozzle clean.

Removing Old Cabin Laminate from Composite

1. Apply Cee-Bee[®] A-918 to the old cabin laminate using brushes wet with cleaner.
2. Wait a few minutes.
3. Peel off the old cabin laminate.
4. Clean the adhesive residue with the Cee-Bee[®] A-918.
5. Let it air dry or use hot air to dry it completely out of the porous composite.
6. Before it is completely dry, do not apply new cabin laminate.

Label Removal

1. Apply Cee-Bee[®] A-918 to the labels/adhesive residues using brushes wet with cleaner.
2. Wait 30 seconds to one minute.
3. Peel off label.

Removal of Adhesive Residue

1. Apply Cee-Bee[®] A-918 to adhesive residue using scrubbing pads or cloth wet with cleaner.
2. Wipe the surface clean with scrubbing pads or cloth wet with cleaner.
3. Allow to air dry or wipe with clean, dry cloths.

Safety, Handling, and Precautions

- **DANGER!** Contains chlorinated hydrocarbons.
- Avoid contact with skin and eyes. Wear solvent resistant gloves and goggles or face shield.
- Avoid prolonged exposure to vapors. Provide adequate ventilation.
- Do not take internally.
- For contact with eyes or skin, flood with water. If irritation persists, seek medical attention.
- For inhalation remove to fresh air.
- Open container slowly to avoid spewing of contents. Store in cool dry area. Keep containers tightly sealed.
- Before using on plastic, electrical insulation or a painted surface that might be damaged, check effect on samples.

Contact Us

United States

McGean

Phone: +1-216-441-4900

Fax: +1-216-441-1377

Email: Aviation@McGean.com

United Kingdom

McGean-Rohco (UK) Ltd.

Phone: +44-1902-456563

Fax: +44-1902-457443

Email: Aviation@McGean-Rohco.co.uk

Singapore

McGean Singapore

Phone: +65-6863-2296

Fax: +65-6863-2297

Email: Info@ceebee.com.sg

China

Cee-Bee Aviation Materials (Xiamen) Co. Ltd.

Phone: +86-592-551-3689

Email: Info@ceebee.com.cn

Cee-Bee[®] A-918 is a wipe solvent used to remove fingerprints, rubber and primer residues, marking inks, wax films, oils and grease from metal surfaces. Cee-Bee[®] A-918 is also good in removing label/adhesive residues.

CAUTION: BEFORE USING ANY OF THESE PRODUCTS, YOU MUST BECOME COMPLETELY FAMILIAR WITH THE INFORMATION CONTAINED IN MCGEAN'S SAFETY DATA SHEETS. All information contained therein or in this document regarding handling, personal protection, and other safety measures must be followed during use. McGean presents the information herein without warranty and disclaims any liability, including any consequential, special, or indirect damages, arising from its use and misuse. Because the use, the conditions of use, product or product composition, and/or applicable laws may differ from one location to another and/or may change with time, the purchaser and/or user is solely responsible for determining whether the product is appropriate for use. McGean recommends use of this product solely in commercial processes which are specified by McGean and which do not violate any third-party patent rights or any laws or regulations or otherwise adversely impact human health and the environment. Users must make their own investigations and determine the suitability of the product for their particular purposes. McGean does not guarantee the accuracy of any data provided by its suppliers. MCGEAN MAKES NO WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE EXCEPT AS EXPRESSLY STATED IN THE SELLER'S SALES CONTRACT OR SALES ACKNOWLEDGEMENT FORM. USE OF ANY MCGEAN PRODUCT IS AT THE USER'S RISK.



Revision: 06/2021